


Uponor Smatrix Move PRO SPI Sensor Snow S-158









QUICK GUIDE




<https://www.uponor.com/smatrix/downloads.aspx>





2




3




X-159






X-159





4




X-159



X-159



5



NEMA 6P / IP 68



-50...70 °C



6 x 0.15 mm² (≤25 m)



NTC 10
-50 °C...+100 °C, ±0.1 °C



220 Ω +/- 10%
0,1 A @24V

R_{OFF} = ∞ Ω
R_{ON} < 2MΩ